



**Figure 1.** Percentage cover of fouling organisms on different parts of the hull within each of three successional categories, as determined by analyses of video footage taken for hull inspections of merchant vessels visiting New Zealand. Values are means  $\pm$  1. SE.